

A . ALGEO LTD

SHERIDAN HOUSE BRIDGE INDUSTRIAL ESTA' SPEKE HALL ROAD LIVERPOOL ENGLAND L24 9HB

MATERIAL SAFETY DATA SHEET

Date of Issue: 20th. March 2000 Data Sheet Ref:

1. Product Identification

Hirschkleber Craft Paste

2. Hazardous Ingredients

There are no hazardous ingredients as defined in OSHA 1910.1200. This product should NOT be considered hazardous at ambient temperatures. It is inert and non-toxic in *normal* handling conditions. Hirschklener Adhesive contains no toxic chemicals subject to the reporting requirements of Section 313 of the Emergency Planning and Community Right-to-know Act of 1996 and of 40 CPR 372.

3. Physical Data

Physical State Boiling Point

Vapour Pressure @ 20 Deg.C

Vapour Density Percentage Volatiles

Appearance Solubility in Water Evaporation Rate

pH Odour Constituents Semi Solid Not applicable

N/A N/A

Less than 0.5%

Off-grey Negligible N/A N/A None

Potato dextrins and Preservatives

4. Fire and Explosion Hazard Data

Auto Ignition Temperature Extinguishing Media

Special Fire Fighting Procedures

Unusual Fire & Explosion Hazards

Hazardous products of Combustion

Not Applicable.

Water, Carbon Dioxide, Dry Foam Standard Procedure for Class A Fires, (Use self-contained breathing apparatus) Latex, like all Rubbers, may generate

dense smoke in a fire.

Carbon Monoxide, Carbon Dioxide, Oxides of Nitrogen, Some organic volatiles, and traces of incompletely burned carbon compounds

5. Health Hazard Data

Effects of over exposure

None are expected with normal handling. Static electrical charges, which may discharge through the operators, causing minor discomfort. Cutting and grinding may produce nuisance dust.

Threshold Limit Value

Emergency & First Aid Procedures

Inhalation: Eye Contact: Skin Contact: Ingestion: Not established

Seek Medical Attention if necessary

Remove to fresh air. Flush with Water

Wash with Soa E&: Water + 44 (0) 15 1-448 1

Not applicabl∉AX:

+44 (0) 151-448 I

website: r email: a

website: http://www.algeos

ail: algeolpl@msn.con
Registered in England No. 4

6. REACTIVITY DATA

Stability Conditions to Avoid

None

Incompatibility (Materials to Avoid)

Avoid contact with concentrated acids.

Hazardous Polymerisation

Will not occur.

7. SPILL OR LEAK PROCEDURES

STEPS to be taken if material is released or spilled:

If material is NOT contaminated, it can

be wiped and used.

Disposal must be done in accordance

WASTE DISPOSAL METHOD:

is recommended.

with relevant regulation. Sanitary landfill

8. SPECIAL PROTECTION INFORMATION

Appropriate Hygienic Practices

Avoid breathing fibres or dust. Wash thoroughly after handling and before eating, drinking or smoking. Remove contaminated clothing and clean before reuse.

Personal Protective Equipment

When processing (e.g. Cutting, grinding), wear appropriate dust mask, impervious gloves, Safety Glasses and appropriate

protective clothing.

Engineering Controls

Adequate ventilation should be provided during processing.

9. LABELLING (CPL REGULATIONS 1984)

Not Classified

10. STORAGE

Store in a dry place at a temperature between 5 Deg.C.and 27 Deg.C. Store away from Heat and Foodstuffs. Store out of Direct Sunlight. As with most materials, off-cuts and discarded wastes should not be allowed to accumulate in loose piles. Good housekeeping practices are always important.

The information contained herein is furnished without warranty of any kind. Product users should make independent judgements of suitability of this information to ensure proper use and protect the Health & Safety of employees.

Before using any product, the label should be carefully read and current literature and information relating to the product consulted.